

POLAR SERVICE

DESCRIPTION		PRICE (excl GST)
SERVICE CHARGES		
General service	Includes battery change (watch unit), 'O'ring replacement, pressure test and transmitter test.	\$ 40.00
	Watch strap replacement (non-metal) + freight charges	\$ 15.00
Wearlink service	Includes battery change, test and clean	\$ 15.00
Trouble Shooting	For trouble shooting, help or software upgrades, contact: www.support.polar.fi	
Pat Langevad	Service Manager	09 306 7227
Jeff McNamara	Service Centre	09 306 7229
	SERVICE ADDRESS:	
	Polar Service Centre	
	24 Heather Street	
	Parnell, Auckland 1052	
	PO Box 1438	Tel 09 306 7200
	Auckland 1140	fax 09 379 0281

POLAR®